



ENVIRONMENTAL ASSISTANCE GROUP

P.O. Box 2537 TEHACHAPI, CA 93581

PHONE/FAX 661-822-8762 E-MAIL comply@haztrainer.com

REPORT ASBESTOS AND LEAD OF THE ATHELETIC FIELD PUMP SHED AND ELECTRICAL VAULT/STORAGE ROOMS

Conducted at

EL MONTE HIGH SCHOOL
3048 NORTH TYLER AVENUE
EL MONTE, CALIFORNIA 91732

Prepared for

MS. NORMA MACIAS, DIRECTOR OF FACILITIES, MAINTENANCE, OPERATIONS
AND TRANSPORTATION
EL MONTE UNION HIGH SCHOOL DISTRICT

Prepared by

ENVIRONMENTAL ASSISTANCE GROUP,
PO BOX 2537
TEHACHAPI, CA 93581

Project Number: MEMHE317
March 29, 2017

Report generated by

Eldwin "Ed" Kennedy, CAC # 93-1429 CLP # 4092
President
Environmental Assistance Group

REPORT OF ASBESTOS AND LEAD SAMPLE COLLECTION

INTRODUCTION

On March 28, Environmental Assistance Group represented by Ed Kennedy, collected samples of suspect Asbestos and Lead materials at El Monte High School in the El Monte Union High School District.

Samples were taken of exterior building materials on the athletic field pump house and the electrical vault with the two attached north and south storage sheds.

Suspect asbestos samples were taken including roofing materials and the white textured paint on the concrete wall of the electrical vault.

Suspect lead containing samples were taken of the blue paint on the wood fascia and door of the pump shed and on the fascia of the electrical vault and storage buildings. Blue paint on the old metal doors of the vault was also sampled. White paint was sampled on the block walls of the storage buildings and on the concrete walls of the electrical vault.

METHOD

The sampling method for Asbestos, included cutting or scraping off sections of the materials and placing them in a sealed container to be sent to the lab for analyses.

The sampling method for Lead included collecting approximately one square inch section of painted surface coating through all layers, all the way to the substrate.

The samples were placed in leak tight hard shell containers and transported to a NVLAP and DHS certified laboratory, Forensic Analytical, for analysis by Polarized Light Microscopy (PLM Asbestos) and Flame Atomic Absorption (Lead). A chain of custody was attached to the sample submittal sheets. A report of analyses results was provided for inclusion in this report.

RESULTS

The analyses of materials for Asbestos showed that the materials sampled do not contain asbestos.

The analysis of paint for Lead showed that the some of the paint sampled did have enough lead content to be considered lead based paint, above the lead based paint definition of 0.06% lead by weight. The blue fascia and door paint on the pump shed and the blue paint on the old metal doors of the electrical vault, contain lead at .65% and 12% respectively. The white paint on the concrete walls of the electrical vault contain .17% lead.

RECOMMENDATIONS

No special handling of the roofing or textured paint is required because of negative asbestos content.

The blue loose and peeling paint on the pump shed wood surfaces and the white paint on the concrete walls of the electrical vault must be at minimum stabilized by trained and certified lead abatement workers using approved paint chip and dust control methods. Pre-notification to OSHA should be made. Debris should be contained and tested prior to disposal to determine disposal method. Workers disturbing materials with any level of lead should have at minimum Lead Hazard Communication training

.

HOMOGENEOUS AREA/SAMPLING FORM

Page 1 of 1

CLIENT: MERGE/EMUHSD

Environmental Assistance Group
PO Box 2537 Tehachapi, CA 93581
Office: 661-822-8762

DATE: 3-28-17

SITE: EL Monte High School

PROJECT # MEMHE317

SAMPLED: 3-28-17

CERT/CAC #: 93-1249

INSPECTOR: Eldwin "Ed" Kennedy

Signature: Eldemir Ekmecy

[illegible]

Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

Environmental Assistance Group
Ed Kennedy
PO Box 2537

Tehachapi, CA 93561

Client ID: L1206
Report Number: B236904
Date Received: 03/28/17
Date Analyzed: 03/29/17
Date Printed: 03/29/17
First Reported: 03/29/17

Job ID/Site: El Monte H.S.

FALI Job ID: L1206
Total Samples Submitted: 2
Total Samples Analyzed: 2

Date(s) Collected:

Sample ID	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
EMH1	51050899						
Layer: Silver Paint			ND				
Layer: Black Tars			ND				
Layer: Black Felts			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)	Fibrous Glass (10 %)	Synthetic (55 %)					
EMH2	51050900						
Layer: Paint/Coating			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							



Tiffani Ludd, Laboratory Supervisor, Rancho Dominguez Laboratory

Note: Limit of Quantification ('LOQ') = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'.

Analytical results and reports are generated by Forensic Analytical Laboratories Inc. (FALI) at the request of and for the exclusive use of the person or entity (client) named on such report. Results, reports or copies of same will not be released by FALI to any third party without prior written request from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by FALI. The client is solely responsible for the use and interpretation of test results and reports requested from FALI. Forensic Analytical Laboratories Inc. is not able to assess the degree of hazard resulting from materials analyzed. FALI reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. All samples were received in acceptable condition unless otherwise noted.



Forensic Analytical Laboratories, Inc.
(COC)

Analysis Request Form

Client Name & Address: Environmental Assistance Group PO Box 2537 Tehachapi CA 93281		Client No.: 11206	PO / Job#: Date: 3-28-17
Contact: Ed Kennedy Phone: Office: 661-822-8762 Fax: Cell: 661-354-8961 661-822-8762		Turn Around Time: Same Day / <u>1 Day</u> / 2 Day / 3 Day / 4 Day / 5 Day	
Email: comply@HazTrainer.com		<input checked="" type="checkbox"/> PPM <input type="checkbox"/> MOSH 7400A / <input type="checkbox"/> MOSH 7400B <input type="checkbox"/> Rotameter <input checked="" type="checkbox"/> PLM <input type="checkbox"/> Standard / <input type="checkbox"/> Point Count 400 - 1500 / <input type="checkbox"/> OGRE 495 <input type="checkbox"/> TEM Air <input type="checkbox"/> AHERA / <input type="checkbox"/> Yantrex2 / <input type="checkbox"/> MOSH 7402 <input type="checkbox"/> TEM Bulk <input type="checkbox"/> Quantitative / <input type="checkbox"/> Qualitative / <input type="checkbox"/> Chatfield <input type="checkbox"/> TEM Water <input type="checkbox"/> Potable / <input type="checkbox"/> Non-Potable / <input type="checkbox"/> Weight % <input type="checkbox"/> TEM Microvac <input type="checkbox"/> Cushtest / <input type="checkbox"/> D5755 (strength) / <input type="checkbox"/> D5756 (strength) <input type="checkbox"/> IQ Particle Identification (PLM LAB) <input type="checkbox"/> PLM Opaques/Spill <input type="checkbox"/> Particle Identification (TEM LAB) <input type="checkbox"/> Special Project <input type="checkbox"/> Metals Analysis: Method:	
Site Location: E1 Monte HS		Matrix: _____ Analytes: _____	

Comments:				Report Via: <input type="checkbox"/> Fax <input checked="" type="checkbox"/> E-Mail <input type="checkbox"/> Verbal				
FA	Sample ID	Date / Time	Sample Location / Description	Type	Time On/Off	Avg. LPM	Total Time	Sample Area / Air Volume
	EMH 1			A P C				
	EMH 2			A P C				
				A P C				
				A P C				
				A P C				
				A P C				
				A P C				
				A P C				
				A P C				
				A P C				

Sampled By: Edwin Kennedy EK		Date: _____ Time: _____	
Shipped Via: <input type="checkbox"/> Fed Ex <input type="checkbox"/> DHL <input type="checkbox"/> UPS <input type="checkbox"/> US Mail <input type="checkbox"/> Courier <input checked="" type="checkbox"/> Drop Off <input type="checkbox"/> Other:			
Requisitioned By: Edwin Kennedy EK	Relinquished By: _____	Requisitioned By: _____	
Date / Time: 3-28-17	Date / Time: _____	Date / Time: _____	
Received By: Carla D/O	Received By: _____	Received By: _____	
Date / Time: 3/28/17 5:14p	Date / Time: _____	Date / Time: _____	
Condition Acceptable? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Condition Acceptable? <input type="checkbox"/> Yes <input type="checkbox"/> No	Condition Acceptable? <input type="checkbox"/> Yes <input type="checkbox"/> No	

San Francisco Office: 2777 Decot Road, Suite 405 Hayward, California 94545-2761 / Ph: (510) 887-8828 / (800) 327-3274 / Fax: (510) 887-4218
 Los Angeles Office: 2959 Pacific Commerce Drive, Rancho Dominguez, California 90221 / Ph: (310) 763-2574 / (858) 513-0417 / Fax: (310) 763-4400
 Las Vegas Office: 6785 S. Eastern Avenue, Suite 3, Las Vegas, Nevada 89119 / Ph: (702) 764-2040 / Fax: (702) 764-2020

LEAD SAMPLING FORM

Page 1 of 1

CLIENT: MERGE/EMUHSD

Environmental Assistance Group
PO Box 2537 Tehachapi, CA 93581
Office: 661-822-8762

DATE: 3-28-17

SITE: El Monte High School

PROJECT # MEMHE317

SAMPLED: 3-28-17

LEAD CERT #: 4092

INSPECTOR: Eldwin "Ed" Kennedy

Signature: Elmari E Kennedy

[illegible]

Metals Analysis of Bulks - TTLC

Environmental Assistance Group
Ed Kennedy
PO Box 2537

Tehachapi, CA 93561


Client ID: L1206
Report Number: M183227
Date Received: 03/28/17
Date Analyzed: 03/29/17
Date Printed: 03/29/17
First Reported: 03/29/17

Job ID / Site: El Monte H.S.
Date(s) Collected:

FALI Job ID: L1206
Total Samples Submitted: 6
Total Samples Analyzed: 6

Sample Number	Lab Number	Analyte	Result	Result Units	Reporting Limit*	Method Reference
EMH 1	LM139112	Pb	6500	mg/kg	300	EPA 3050B/7000B
Comment:	Insufficient sample size for repeatable analysis.					
EMH 2	LM139113	Pb	120	mg/kg	60	EPA 3050B/7000B
Comment:	Insufficient sample size for repeatable analysis.					
EMH 3	LM139114	Pb	120000	mg/kg	6000	EPA 3050B/7000B
Comment:	Insufficient sample size for repeatable analysis.					
EMH 4	LM139115	Pb	130	mg/kg	70	EPA 3050B/7000B
Comment:	Insufficient sample size for repeatable analysis.					
EMH 5	LM139116	Pb	23	mg/kg	8	EPA 3050B/7000B
EMH 6	LM139117	Pb	1700	mg/kg	200	EPA 3050B/7000B

* The Reporting Limit represents the lowest amount of analyte that the laboratory can confidently detect in the sample, and is not a regulatory level. The Units for the Reporting Limit are the same as the Units for the Final Results.



Beatriz Hinojosa, Laboratory Supervisor, Rancho Dominguez Laboratory

Analytical results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) named on such report. Results, reports or copies of same will not be released by Forensic Analytical to any third party without prior written request from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by Forensic Analytical. The client is solely responsible for the use and interpretation of test results and reports requested from Forensic Analytical. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed. Forensic Analytical reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. Any modifications that have been made to referenced test methods are documented in Forensic Analytical's Standard Operating Procedures Manual. Sample results have not been blank corrected. Quality control and sample receipt condition were acceptable unless otherwise noted.

San Francisco Office: 3777 Doolittle Road, Suite 400, Emeryville, California 94605-2766 / Ph: (510) 547-8626 / (800) 327-3274 / Fax: (510) 837-4218
 Los Angeles Office: 2959 Pacific Commerce Drive, Bannockburn, California 90221 / Ph: (310) 833-2174 / (800) 813-0417 / Fax: (310) 765-4450
 Las Vegas Office: 6765 S. Eastern Avenue, Suite 1, Las Vegas, Nevada 89119 / Ph: (702) 784-0040 / Fax: (702) 784-6300